

Client: City of Stamford Mold Task Force Job Number: S-2087-033

**Site:** Julia A. Stark Elementary School







**Description:** Cafeteria Entryway—Water Stained Drywall Above Ceiling Tiles



Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School






Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School

Photograph No.: 5 | Date: 11/14/18 | Direction Taken: -

**Description:** Gymnasium— Water Damaged Wood Flooring




Photograph No.: 6 Date: 11/14/18 Direction Taken: —

**Description:** Stage—Water Damaged and Growth Impacted Ceiling Drywall



Client: City of Stamford Mold Task Force Job Number: S-2087-033

**Site:** Julia A. Stark Elementary School






Client: City of Stamford Mold Task Force

**Site:** Julia A. Stark Elementary School

**Job Number:** S-2087-033

Photograph No.: 9 Date: 11/14/18 Direction Taken: —

Description: Room 220—Water Stained and Damaged Ceiling Plaster above Ceiling Tiles




Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School

Photograph No.: 11 Date: 11/14/18 Direction Taken: —

**Description:** Room 230—Water Stained and Damaged Ceiling Plaster above Ceiling Tiles



Photograph No.: 12 Date: 11/14/18 Direction Taken: —

Description: Corridor at Room 230—Black Growth Impacted Drywall Behind Vinyl Wallcovering




Client: City of Stamford Mold Task Force Job Number: S-2087-033

**Site:** Julia A. Stark Elementary School

Photograph No.: 13 Date: 11/14/18 Direction Taken: —

Description: Room 234 — Condensation and Corrosion on Structural Steel



Client: City of Stamford Mold Task Force Job Number: S-2087-033

**Site:** Julia A. Stark Elementary School

Photograph No.: 15 Date: 11/14/18 Direction Taken: —

**Description:** Room 252 — Black Growth on Window Jamb Drywall



Photograph No.: 16 Date: 11/14/18 Direction Taken: —

Description: Room 252—Black Growth on Window Header



Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School

Photograph No.: 17 Date: 11/14/18 Direction Taken: —

**Description:** Room 252 — Water Damaged and Growth Impacted Drywall Behind Wallcovering



Photograph No.: 18 Date: 11/14/18 Direction Taken: —

Description: Room 168—Water Stained and Growth-Impacted Drywall at Window Header



Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School

Photograph No.: 19 Date: 12/26/18 Direction Taken: —

Description: Corridor b/t Room 219 & 211—Growth Impacted Drywall behind Vinyl Wallcovering



Photograph No.: 20 Date: 11/14/18 Direction Taken: —

**Description:** Corridor Wall at Room 212 Kiln Room—Growth Impacted Drywall (Prior to Cleaning)



Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School

Photograph No.: 21 Date: 12/26/18 Direction Taken: —

**Description:** Corridor Wall at Room 212 Kiln Room—Growth Impacted Drywall (Post-Cleaning)



Photograph No.: 22 Date: 12/26/18 Direction Taken: —

**Description:** Corridor b/t Room 219 & 211—Post-Removal Growth Impacted Drywall



**Client:** City of Stamford Mold Task Force

Site: Julia A. Stark Elementary School

**Job Number:** S-2087-033

Photograph No.: 23 Date: 12/26/18 Direction Taken: —

Description: Corridor b/t Room 2003 & 246 —Growth Impacted Drywall behind Vinyl Wallcovering



Photograph No.: 24 Date: 12/26/18 Direction Taken: —

**Description:** Corridor b/t Room 203 & 246— Black Growth on Fiberglass Insulation Behind Drywall



Client: City of Stamford Mold Task Force

Site: Julia A. Stark Elementary School

**Job Number:** S-2087-033

Photograph No.: 25 | Date: 12/26/18 | Direction Taken: -

**Description:** Corridor b/t Room 203 and 246—Post-Removal Growth Impacted Drywall



Photograph No.: 26 Date: 12/26/18 Direction Taken: —

Description: Corridor b/t Room 103 & 117— Growth Impacted Drywall behind Vinyl Wallcovering



Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School

Photograph No.: 27 | Date: 12/26/18 | Direction Taken: —

Description: Corridor b/t Room 103 & 117— Growth Impacted Drywall behind Vinyl Wallcovering



Photograph No.: 28 Date: 12/26/18 Direction Taken: —

**Description:** Corridor b/t Room 103 & 117—Post-Removal Growth Impacted Drywall



Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Julia A. Stark Elementary School

