## **Site Assessment—Photographic Log**




Client: City of Stamford Mold Task Force

**Site:** KT Murphy—Elementary School

**Job Number:** S-2087-033

Photograph No.: 1 Date: 5/29/19 Direction Taken: —

Description: Kitchen Custodian Closet—Uninsulated Piping



Photograph No.: 2 Date: 5/29/19 Direction Taken: —

**Description:** Kitchen Custodian Closet—Asbestos Flooring



## **Site Assessment—Photographic Log**



Client: City of Stamford Mold Task Force

**Site:** KT Murphy—Elementary School

**Job Number:** S-2087-033

Photograph No.: 3 | Date: 5/29/19 | Direction Taken: -

**Description:** Gym Office—Damaged Wall Plaster and Growth Impacted Drywall



Photograph No.: 4 Date: 5/29/19 Direction Taken: —

**Description:** Kitchen Custodian Closet—Wood Paneling Over Water/Growth-Impacted Drywall

