

Tighe&Bond

Client: City of Stamford Mold Task Force

Site: KT Murphy—Elementary School

Job Number: S-2087-033





Tighe&Bond

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: KT Murphy—Elementary School


Photograph No.: 3 Date: 11/2/18 Direction Taken: —

Description: "Wet" Carpet—Front Portion of Media Center



Photograph No.: 4 Date: 11/2/18 Direction Taken: —

Description: Visible Water at Skylight—Media Center



Tighe&Bond

Client: City of Stamford Mold Task Force

Site: KT Murphy—Elementary School

Job Number: S-2087-033

Photograph No.: 5 Date: 11/5/18 Direction Taken: —

Description: Vegetative Growth at Skylight—Exterior Roof



Photograph No.: 6 Date: 11/5/18 Direction Taken: —

Description: Deteriorated Caulking/Flashing at Skylight— Exterior Roof



Tighe&Bond

Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: KT Murphy—Elementary School

Photograph No.: 7 | Date: 11/2/18 | Direction Taken: -

Description: Water Stained Ceiling Tiles—Book Room



Photograph No.: 8 Date: 11/5/18 Direction Taken: —

Description: Water Stained Wood Blocking above Ceiling—Book Room





Tighe&Bond

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: KT Murphy—Elementary School





Tighe&Bond

Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: KT Murphy—Elementary School

Photograph No.: 11 Date: 11/2/18 Direction Taken: —

 $\textbf{Description:} \ \mathsf{Peeling} \ \mathsf{Paint} - \mathsf{Corridor} \ \mathsf{at} \ \mathsf{Room} \ \mathsf{12}$



Photograph No.: 12 Date: 11/2/18 Direction Taken: —

Description: Water Stained and Black Growth on Ceiling Tiles— Basement Corridor Closet



Tighe&Bond

Client: City of Stamford Mold Task Force

Site: KT Murphy—Elementary School

Job Number: S-2087-033

Photograph No.: 13 Date: 11/2/18 Direction Taken: —

Description: Standing Water in Sump Pump—Auditorium Sump Pump Closet



Photograph No.: 14 Date: 11/2/18 Direction Taken: —

Description: PVC to Cast Iron Connection—Auditorium Sump Pump Closet



Tighe&Bond

Client: City of Stamford Mold Task Force

Site: KT Murphy—Elementary School

Job Number: <u>S-2087</u>-033


Photograph No.: 15 Date: 11/2/18 Direction Taken: —

Description: "Wet" Carpet—Auditorium Entryway



Photograph No.: 16 Date: 11/2/18 Direction Taken: —

Description: Water Stained Plaster Ceiling—Auditorium





Client: City of Stamford Mold Task Force

Site: KT Murphy—Elementary School

Job Number: S-2087-033

Photograph No.: 17	Date: 11/2/18	Direction Taken: —
Description: "Wet" Fo	oam Insulation and Blac	ck Growth—Room 1

Photograph No.:	Date:	Direction Taken:	
Description:			