



Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033



Site: Newfield Elementary School



Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force
Site: Newfield Elementary School

Job Number: S-2087-033



Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force
Site: Newfield Elementary School

Job Number: S-2087-033



Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Newfield Elementary School

Photograph No.: 7	Date: 11/2/18	Direction Taken: —
Description: Peeling Paint on Plaster Horizontal Window Return—Main Office		
		



Photograph No.: 8	Date: 11/2/18	Direction Taken: —
Description: Water Impacted Casework—Media Center		
		

Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Newfield Elementary School



Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Newfield Elementary School

Photograph No.: 11	Date: 11/2/18	Direction Taken: —
Description: Deteriorating Caulking — Exterior Media Center		
		


Photograph No.: 12	Date: 11/2/18	Direction Taken: —
Description: Deteriorating Caulking—Exterior Media Center		
		

Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Newfield Elementary School

Photograph No.: 13	Date: 11/2/18	Direction Taken: —
Description: Black Growth/Insect Damage on Wood Wall Paneling — Auditorium		
		


Photograph No.: 14	Date: 11/2/18	Direction Taken: —
Description: Black Growth/Insect Damage on Wood Paneling—Auditorium		
		

Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Newfield Elementary School

Photograph No.: 15	Date: 11/2/18	Direction Taken: —
Description: Limited Deteriorated Roof Caulking/Flashing — Roof Room 200		
		

Photograph No.: 16	Date: 11/2/18	Direction Taken: —
Description: Limited Deteriorated Roof Caulking/Flashing—Roof Room 204		
		

Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Newfield Elementary School

