

# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033K

**Site:** Cloonan Middle School

<b>Photograph No.:</b> 29	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Ground Floor—Room 111C—Heavy Dust Loading on Supply Air Diffuser		
		

<b>Photograph No.:</b> 30	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Second Floor—Room 321—Mold and Water Staining on Ceiling Tile; Roof Leak		
		

# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033K

**Site:** Cloonan Middle School

<b>Photograph No.:</b> 31	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Second Floor—Room 317—Water Stained Ceiling Tile		



<b>Photograph No.:</b> 32	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Second Floor—Room 317—Roof Drain with Moisture Intrusion		

# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033K

**Site:** Cloonan Middle School



# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033K

**Site:** Cloonan Middle School

<b>Photograph No.:</b> 35	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Main Floor—Room 220—Water Stained Ceiling Tiles below Pipe Penetration of Roof Deck		
		

<b>Photograph No.:</b> 36	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Main Floor—Gymnasium—Moderate to Heavy Dust Loading on Supply Air Diffusers		
		

# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033K

**Site:** Cloonan Middle School

<b>Photograph No.:</b> 37	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Ground Floor—Room 106—Moderate to Heavy Dust Loading on Supply Air Diffusers		
		

<b>Photograph No.:</b> 38	<b>Date:</b> 3-11-19	<b>Direction Taken:</b> NA
<b>Description:</b> Ground Floor—Music Office—Heavy Discoloration on Supply Air Diffusers		
		