

# **EMSL** Analytical, Inc.

29 North Plains Highway, Unit # 4 Wallingford, CT 06492

Tel/Fax: (203) 284-5948 / (203) 284-5978 http://www.EMSL.com / wallingfordlab@emsl.com EMSL Order: 241903989 Customer ID: TIGH62

Customer PO: Project ID:

Attention: Meredith Febbraio Phone: (860) 704-4760

 Tighe & Bond
 Fax:
 (860) 704-4775

 213 Court Street
 Received Date:
 07/23/2019 5:00 PM

 Suite 1100
 Analysis Date:
 07/24/2019

 Middletown, CT 06457
 Collected Date:
 07/22/2019

Project: 28-2087-033U/ SMTF, STAMFORD HIGH SCHOOL, STAMFORD HIGH SCHOOL

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbe	Non-Asbestos		
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	<u>Asbestos</u> % Type	
0722BH-13A	Original building roof-south - fiberboard	Brown Fibrous	65% Cellulose	25% Perlite 10% Non-fibrous (Other)	None Detected	
241903989-0001	insulation-brown	Homogeneous	CEN/ Callulana	20% Perlite	Nama Datastad	
0722BH-13B 241903989-0002	Original building Yellow roof-north - fiberboard Non-Fibrous insulation-brown Homogeneous		65% Cellulose	15% Non-fibrous (Other)	None Detected	
0722BH-13C	Original building	Tan	75% Cellulose	25% Non-fibrous (Other)	None Detected	
241903989-0003	roof-upper at slate roof - fiberboard insulation-brown	Fibrous Homogeneous				
0722BH-14A	Original building	Yellow		100% Non-fibrous (Other)	None Detected	
241903989-0004	roof-south - iso-board insulation-yellow	Non-Fibrous Homogeneous				
0722BH-14B	B Original building Yellov roof-north - iso-board Non-F			100% Non-fibrous (Other)	None Detected	
241903989-0005	insulation-yellow	Homogeneous		4000/ N 57 (57)		
0722BH-15A 241903989-0006	Original building roof-south - tar on concrete deck-black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
		Black		2% Quartz	None Detected	
0722BH-15B 241903989-0007	Original building roof- north - tar on concrete deck-black	Non-Fibrous Homogeneous		98% Non-fibrous (Other)	None Detected	
0722BH-15C	Original building	Black		100% Non-fibrous (Other)	None Detected	
241903989-0008	roof-upper at slate roof - tar on concrete deck-black	Non-Fibrous Homogeneous		, , , , , , , , , , , , , , , , , , ,		
0722BH-16A	Original building Black roof-south - top layer Fibrous		25% Glass	75% Non-fibrous (Other)	None Detected	
241903989-0009	modified roofing-black	Homogeneous				
0722BH-16B 241903989-0010	Original building roof-north - top layer modified roofing-black	Black Non-Fibrous Homogeneous	20% Glass	80% Non-fibrous (Other)	None Detected	
0722BH-16C	Original building	Black		2% Quartz	None Detected	
241903989-0011	roof-upper at slate roof - top layer modified roofing-black	Non-Fibrous Homogeneous		98% Non-fibrous (Other)	None Detected	
0722BH-17A	Original building Black roof-south - wall Fibrous		10% Glass	10% Quartz 80% Non-fibrous (Other)	None Detected	
241903989-0012	modified roofing-black	Homogeneous				
0722BH-17B	Original building roof-upper at slate	Black Fibrous	10% Glass	10% Quartz 80% Non-fibrous (Other)	None Detected	
241903989-0013	roof - wall modified roofing-black	Homogeneous				
0722BH-17C	Original building roof-north - curb	Black Non-Fibrous	2% Cellulose	3% Quartz 95% Non-fibrous (Other)	None Detected	
241903989-0014	modified roofing-black	Homogeneous				
0722BH-18A	Original building roof-south - wall tar	Black Non-Fibrous	5% Cellulose	3% Quartz 77% Non-fibrous (Other)	15% Chrysotile	
241903989-0015	on concrete-black	Homogeneous				

Initial report from: 07/24/2019 18:06:36

EMSL Order: 241903989 Customer ID: TIGH62

Customer PO: Project ID:

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbes	<u>tos</u>	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
0722BH-18B 941903989-0016	Original building roof-upper at slate roof - wall tar on concrete-black				Positive Stop (Not Analyzed)	
722BH-18C	Original building roof-north - curb tar				Positive Stop (Not Analyzed)	
41903989-0017	on concrete-black					
1722BH-19A 41903989-0018	Original building roof-north - tar on older exhaust-black	Black Fibrous Homogeneous	50% Cellulose	50% Non-fibrous (Other)	None Detected	
722BH-19B	Original building	Black	35% Cellulose	65% Non-fibrous (Other)	None Detected	
41903989-0019	roof-south - tar on older exhaust-black	Fibrous Homogeneous	35% Cellulose	05% Non-librous (Other)	None Detected	
722BH-20A	Original building roof-north - pitch	Black Fibrous	25% Cellulose	75% Non-fibrous (Other)	None Detected	
41903989-0020	pocket tar-black	Homogeneous				
722BH-20B	Original building roof-south - pitch	Black Non-Fibrous	25% Cellulose	75% Non-fibrous (Other)	None Detected	
41903989-0021	pocket tar-black	Homogeneous				
1722BH-21A 41903989-0022	Original building roof-north - textured	Gray Non-Fibrous		10% Quartz 90% Non-fibrous (Other)	None Detected	
	concrete wall-tan/gray	Homogeneous		400/ Owests	Non- Betested	
722BH-21B	Original building roof-south - textured concrete wall-tan/gray	Gray Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected	
				1000/ Non fibrous (Other)	None Detected	
722BH-22A 41903989-0024	Original building roof-north - paint on roof cover-silver	Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
722BH-22B	Original building	Silver		100% Non-fibrous (Other)	None Detected	
11903989-0025	roof-north - paint on exhaust-silver	Non-Fibrous Homogeneous		100% Non indicate (Guiler)	None Belosted	
722BH-23A	Original building roof-slate roof - slate	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected	
41903989-0026	shingles-gray	Homogeneous				
722BH-23B	Original building roof-slate roof - slate	Gray Non-Fibrous	2% Cellulose	98% Non-fibrous (Other)	None Detected	
41903989-0027	shingles-gray	Homogeneous				
722BH-24A 41903989-0028	Original building roof-slate roof - paper under slate-black	Black Fibrous Homogeneous	50% Cellulose	50% Non-fibrous (Other)	None Detected	
722BH-24B	Original building		80% Cellulose	20% Non-fibrous (Other)	None Detected	
7 2 2 B П - 2 4 B	roof-slate roof - paper under slate-black	Brown/Black Fibrous Homogeneous	00 /0 Cellulose	20 /0 NOTI-IIDIOUS (OUTEI)	None Detected	
722BH-25A	Original building	Gray		10% Quartz	2% Chrysotile	
41903989-0030	roof-slate roof - lightweight	Non-Fibrous Homogeneous		88% Non-fibrous (Other)	270 0,	
722BH-25B	concrete-white Original building				Positive Stop (Not Analyzed)	
41903989-0031	roof-slate roof - lightweight concrete-white					
722BH-26A	Original building roof-slate roof - tar	Black Fibrous	5% Cellulose	5% Quartz 78% Non-fibrous (Other)	12% Chrysotile	
241903989-0032	below bottom late line-black	Homogeneous		7070 Non-Ilbious (Ottiel)		

Initial report from: 07/24/2019 18:06:36



EMSL Order: 241903989 Customer ID: TIGH62

Customer PO: Project ID:

#### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-A	Asbestos	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
0722BH-26B	Original building roof-slate roof - tar				Positive Stop (Not Analyzed)	
241903989-0033	below bottom late line-black					
0722BH-27A	Original building	Black		90% Non-fibrous (Other)	10% Chrysotile	
	roof-slate roof - slate	Non-Fibrous				
241903989-0034	seam tar-black	Homogeneous				
0722BH-27B	Original building				Positive Stop (Not Analyzed)	
	roof-slate roof - slate					
241903989-0035	seam tar-black					

Analyst(s)

Leslie Tetrick (15) Quetcy Castro Romero (15) Almedina Hodzic Ashestos Laboratory Manager

Almedina Hodzic, Asbestos Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0,

Initial report from: 07/24/2019 18:06:36



Tighe & Bond

Attention: Meredith Febbraio

29 North Plains Highway, Unit # 4 Wallingford, CT 06492

Tel/Fax: (203) 284-5948 / (203) 284-5978 http://www.EMSL.com / wallingfordlab@emsl.com

Phone: (860) 704-4760

Fax: (860) 704-4775

Received Date: 07/23/2019 5:00 PM

EMSL Order: 241903989

Customer ID: TIGH62

**Customer PO:** 

Project ID:

213 Court Street Suite 1100 **Analysis Date:** 07/25/2019 Middletown, CT 06457 Collected Date: 07/22/2019

Project: 28-2087-033U/SMTF, STAMFORD HIGH SCHOOL, STAMFORD HIGH SCHOOL

#### Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
0722BH-15A 241903989-0006	Original building roof-south - tar on concrete deck-black	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
0722BH-16A 241903989-0009	Original building roof-south - top layer modified roofing-black	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
0722BH-17A 241903989-0012	Original building roof-south - wall modified roofing-black	Black Fibrous Homogeneous	99.74 Other	None	0.26% Chrysotile
0722BH-19A 241903989-0018	Original building roof-north - tar on older exhaust-black	Black Fibrous Homogeneous	99.75 Other	None	0.25% Chrysotile
0722BH-20A 241903989-0020	Original building roof-north - pitch pocket tar-black	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

Analyst(s)	
Almedina Hodzic (5)	

Almedina Hodzic, Asbestos Laboratory Manager

or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT

Initial report from: 07/25/2019 16:47:42

OrderID: 241903989



241903989

213 Court Street, Suite 1100, Middletown, CT 06457

Phone 860-704-4760

# **SAMPLE LOG FOR ASBESTOS BULKS**

Sheet 1 of 3


Project Name: <u>SMTF - Stamford High School</u>

Project No. <u>28-2087-033U</u>

Building: Stamford High School

Project Manager: Meredith Febbraio

Sample ID	Material Description	Color	Sample Location
0722BH-13A	Original Building Roof – South	Brown	Fiberboard Insulation
0722BH-13B ,	Original Building Roof – North	Brown	Fiberboard Insulation
0722BH-13C	Original Building Roof – Upper at Slate Roof	Brown	Fiberboard Insulation
0722BH-14A	Original Building Roof - South	Yellow	Iso-Board Insulation
0722BH-14B	Original Building Roof – North	Yellow	Iso-Board Insulation
*0722BH-15A	Original Building Roof - South	Black	Tar on Concrete Deck
0722BH-15B	Original Building Roof - North	Black	Tar on Concrete Deck
0722BH-15C	Original Building Roof – Upper at Slate Roof	Black	Tar on Concrete Deck
*0722BH-16A	Original Building Roof – South	Black	Top Layer Modified Roofing
0722BH-16B	Original Building Roof – North	Black	Top Layer Modified Roofing
0722BH-16C	Original Building Roof – Upper at Slate Roof	Black	Top Layer Modified Roofing
*0722BH-17A	Original Building Roof - South	Black	Wall Modified Roofing
0722BH-17B	Original Building Roof – Upper at Slate Roof	Black	Wall Modified Roofing
0722BH-17C	Original Building Roof – North	Black	Curb Modified Roofing
*0722BH-18A	Original Building Roof – South	Black	Wall Tar on Concrete
0722BH-18B	Original Building Roof – Upper at Slate Roof	Black	Wall Tar on Concrete
0722BH-18C	Original Building Roof – North	Black	Curb Modified Roofing Tar on concrete



OrderID: 241903989



24/903989

213 Court Street, Suite 1100, Middletown, CT 06457

Phone 860-704-4760

Sheet 2 of 3

## SAMPLE LOG FOR ASBESTOS BULKS

\_\_\_\_

Project Name: <u>SMTF - KT Murphy</u>

Project No. <u>28-2087-033E</u>

Building: KT Murphy Elementary School Project Manager: Meredith Febbraio

Sample ID	Material Description	Color	Sample Location
*0722BH-19A	Original Building Roof – North	Black	Tar on Older Exhaust
0722BH-19B	Original Building Roof - South	Black	Tar on Older Exhaust
*0722BH-20A	Original Building Roof – North	Black	Pitch Pocket Tar
0722BH-20B	Original Building Roof – South	Black	Pitch Pocket Tar
0722BH-21A	Original Building Roof – North	Tan/Gray	Textured Concrete Wall
0722BH-21B	Original Building Roof – South	Tan/Gray	Textured Concrete Wall
0722BH-22A	Original Building Roof – North	Silver	Paint on Roof Cover
0722BH-22B	Original Building Roof – North	Silver	Paint on Exhaust
0722BH-23A	Original Building - Slate Roof	Gray	Slate Shingles
0722BH-23B	Original Building - Slate Roof	Gray	Slate Shingles
0722BH-24A	Original Building - Slate Roof	Black	Paper Under Slate
0722BH-24B	Original Building - Slate Roof	Black	Paper Under Slate
0722BH-25A	Original Building - Slate Roof	White	Lightweight Concrete
0722BH-25B	Original Building - Slate Roof	White	Lightweight Concrete
*0722BH-26A	Original Building - Slate Roof	Black	Tar Below Bottom Slate Line
0722BH-26B	Original Building - Slate Roof	Black	Tar Below Bottom Slate Line
*0722BH-27A	Original Building - Slate Roof	Black	Slate Seam Tar
0722BH-27B	Original Building - Slate Roof	Black	Slate Seam Tar

P:\Business Lines\Environmental\HBM Team\Standardization Group\HBMA COCs\MTO\TigheBond MTO ACM Bulk Sample For COC. 2018.doc

OrderID: 241903989



241903989

213 Court Street, Suite 1100, Middletown, CT 06457

Method of Shipment: ☐ Overnight (Check one: Fed Ex / UPS) ☐ Other

Phone 860-704-4760

Sheet 3 of 3

S	Δ	M	DI	F	10	G	FOR	Δ	SBES1	COS	RIII	KS
	~				$-\mathbf{c}$	u		$\boldsymbol{m}$	JULJI		DUL	. ~

Project Name: <u>SMTF – Stamford High School</u>	Project No. <u>28-2087-033U</u>						
Building: Stamford High School	Project Manager: <u>Meredith Febbr</u>	raio					
TOTAL # OF SAMPLES:	State sample collected in: CT	_					
Analysis Method: 🛛 PLM 🔲 TEM-NOB 🔲 Point C	Г - 400 🔲 Other						
Turnaround Time (check one): 🗌 3-hr 🔲 6-hr 🔲 2	24-hr 🗌 48-hr 📗 72-hr 📗 96-hr	☐ 1-week ☐ 2-week					
Please call the office if analyses will be late at:							
Email Results to: <u>@tighebond.com</u> <u>Do No</u>	t Mail Hard Copy Report						
Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. Do Not Point Count. If NOB group sample results are 0% - < 1% by PLM, analyze only "A" group sample above by TEM NOB, per group, as noted by asterisk and bold front.							
Samples collected by: Bob Hobbin 5	Date: _ / 22-/9	Time:					
Samples Relinquished by $_{\mathcal{B}}\mathcal{H}$	21.11.12						
Samples Received by:	Date:	Time:					
Shipped To: 🛛 EMSL State CT 📗 Oth	er						

