

Playground Maintenance Corp. dba Playground Medic 146 Broadway Hawthorne, NY 10532

(914)741-2228 Fax (914)747-3965 Toll Free (866)332-3133 E-mail: info@playgroundmedic.com

PLAYGROUND SAFETY INSPECTION REPORT

DATE:	May 16, 2019
SITE:	Newfield Elementary School 345 Pepper Ridge Road Stamford, CT 06905
CLIENT:	Stamford Public Schools Attention: Rich Lyons 888 Washington Boulevard Stamford, CT 06901
CONTACT PHONE NO.	203-977-4105
DATE OF INSPECTION:	April 25, 2019
INSPECTOR:	Natale Chionchio CPSI Certification # 41619-0521

Expiration: 5/1/2021

PURPOSE AND DEFINITIONS

PURPOSE

The purpose of a Playground Safety Inspection is to:

- * Evaluate the overall condition of a playground or playgrounds at a given facility
- * Identify hazardous conditions needing attention
- * Identify Maintenance issues that the owner should be aware of

HAZARD DEFINITIONS

CLASS A HAZARD: Any condition of the playground that is life threatening or could cause severe, permanent disability.

CLASS B HAZARD: Any condition of the playground that could cause a serious but non-disabling injury.

CLASS C HAZARD: Any condition of the playground that can cause a slight injury or any condition that may not cause injury but does not meet either the Guidelines in the CPSC "Handbook for Public Playground Safety" or the ASTM F1487 "Standard Consumer Safety Performance Specifications for Playground Equipment for Public Use."

MAINTENANCE: Repairs needed or recommendations for improvement

STRUCTURAL STABILITY

When properly installed as directed by the manufacturer's instructions and specifications, equipment should withstand the maximum anticipated forces generated by active use which might cause it to overturn, tip, slide or move in any way.

Stability of play equipment is tested by digging around equipment footings and checking for deterioration or signs of movement that would indicate structural instability.

SURFACING

DEPTH:

The surfacing under and around the playground equipment can be a major factor in determining the injury causing potential of a fall. A fall onto a shock-absorbing surface is less likely to cause a serious injury than a fall onto a hard compacted surface. Inadequate surfacing material is usually a CLASS A HAZARD depending on the surfacing material.

The depth of surfacing material is checked by digging down to the sub base in heavy wear and low wear areas.

USE ZONE:

The surface under and around a piece of equipment onto which a child falling from or exiting from the equipment would be expected to land. These areas are also designated for unrestricted circulation around the equipment.

Use Zone is checked on all equipment by measurements in accordance with CPSC quidelines.

CONDITION EXPLANATION

Equipment and surfacing conditions will be identified as "Good", "Fair" or "Poor". This is a general classification and will indicate:

Good * No Corrective action needed

Fair * Some corrective action needed

Poor * Extensive corrective action needed

NEWFIELD ELEMENTARY SCHOOL Area #1

Overview

This playground is in fair condition. There are equipment and surface hazards and maintenance issues to address.

EQUIPMENT INVENTORY

Large Composite Structure









Manufacturer

Play & Park Structures











Freestanding Equipment
MaxClimb Matrix



Play & Park Structures



MaxClimb Crest



Play & Park Structures



Log Roll



8ft. Swing Set (4 Bays /8 Belt Seats)



Unknown



GameTime



SURFACING MATERIAL



Poured in Place Rubber Engineered Wood Fiber

MANUFACTURER CONTACT INFORMATION

Play & Park Structures

430 Chestnut Street, Suite 300 Chattanooga, TN 37402 888-404-5737 www.parkstructures.com

GameTime

PO Box 680121 Ft. Payne, AL 35968-0121 800-633-2394 www.gametime.com

GENERAL PLAYGROUND ENVIRONMENT

Playground Condition:

FAIR

Area #1_	
----------	--

Gen	neral Site Conditions	Condition	Hazard	Recommendation
1	Playground Location at Facility	Back left side of School		
	Number of footings in area	130		
2	Distance from roads and parking lots	150 feet		
3	Fencing-total, partial, height, type	Total - 6ft.		
4	Traffic or fence hazard	None		
5	Site conditions-level, hill, pitched	Level		
6	Drainage Problems	None		
7	Encroachment of brush or poisonous plants-where	Brush in use zone of swings & log roll	Maint.	Cut back brush to 16ft. from top rail of swings & 6ft. from Log Roll
8	Bees or insects/animals noted	None		
9	Site Amenities-bench, TR, Table Condition	Bench, TR, Table Good		
10	Border/Edging-type	Plastic Ties & Asphalt		
	Condition of edging	Some ties not level	Maint.	Level ties where needed
11	Shade Structure or shade	Roof & trees		
12	Signage Age Appropriate Signs/Stickers?	Yes		
	Equipment Age Appropriate, 2-5, 5-12	5-12 years		

General Site Conditions	Condition	Hazard	Recommendation
Adult Supervision sign or sticker?	Yes		
Warning Signs installed?			
Hard Surface	Yes		
Heat	Yes		
Drawstring/Strangulation	Yes		
Surface Marker signs on uprights?	N/A - PIP Yes - EWF		
Playground Rules & General Information Sign?	No	Maint.	See Notes
13 Accessibility			
Accessible Entrance 60" wide ?	Yes		
Accessible path to play area ?	Yes		
Accessible surface in use zone?	Yes		

Notes:

It is recommended that signs be installed indicating playground rules and general information.

NEWFIELD ELEMENTARY SCHOOL

AREA #1 CONDITION REPORT

	Condition	Hazard Priority	Recommendation
Large Composite Structure (Play & Par		Tilotity	Recommendation
Components	7		
ADA Pedal Pusher	Good		
Pedal Pusher	Good		
Fire Truck Cab	Good		
Ramps (4)	Good		
Swivel Stations (2)	Wheels rattle	Maint.	Lubricate eight wheels
Log Rolls (2)	Good		-
Steering Wheels (5)	Good		
Swoop Step Link	Good		
Button Steps (4)	One step loose at bracket	Maint.	Tighten four bolts below step
Double Trapeze Rings	Ten "S" - Hooks wearing	В	Replace ten "S" - Hooks
Twister	Good		
Tic-Tac-Toe Panel	Panel detached at one bolt	Maint.	Replace one bolt & reattach
Music Panel	Two bolts missing	Maint.	Replace two bolts & reattach to panel
Racing Game Panel	Two levers missing	Maint.	Replace two levers
Apex Single Ladder Attach.	Good		
MaxClimb Ridge Top	Good		
Geo Shapes Panel	Two bolts missing	Maint.	Replace two bolts & reattach
	Stairs over 48" should		
Stairs (1)	have barrier rails, not guardrail	С	Consult MFR.
Benches (3)(below)	Good		
Avalanche Triple Slide	Good		
Wiggle Wave Climber	Good		
Access Two Rung Ladder	Good		
Flower Maze Panel	Graffiti on panel	Maint.	Remove graffiti
Talk Tubes (2)	Good		
Smiley Panel	Good		
Radius Chain Net	Small cracks in plastisol	Maint.	Monitor
Transfer Platform	Good		
Bubble Panel	Broken, sharp edges	В	Replace panel
Spin & Win Panel	Good		•
Mirror Panel	Good		
Cliff Climbers (2)	One panel warped (high cliff)	Maint.	Monitor
	Incorrect hardware at two bolts (lower cliff)	Maint.	Replace with two manufacturers bolts

AREA #1 CONDITION REPORT

			Hazard	
		Condition	Priority	Recommendation
Apex Climbing Attach. 360° Spiral Hurricane Slide		Good Good		
Landslide Slide Storefront Panel (below) Decks (14)		Good Good Good		
Surfacing	PIP 2 - 2¾"	Several cracks, holes, edges lifting, tripping hazard	В	Clean, repair & seal or schedule replacement
		Surface worn, repairs have gaps at edges		
Use Zone		Good		
Structural Stability		Good		
Freestanding Equipment				
MaxClimb Matrix (Play &	Park)	Good		
Surfacing	EWF 7-9"	Low in spots	В	Top off & level
Use Zone		Good		
Structural Stability		Good		
MaxClimb Crest (Play & I	Park)	Good		
Surfacing	EWF 7-9"	Good		
Use Zone		Good		
Structural Stability		Good		

AREA #1 CONDITION REPORT

		Condition	Hazard Priority	Recommendation
Log Roll (Unknown)		Good		
Surfacing	EWF 8-10"	Good		
Use Zone		Brush in rear use zone 4ft. from unit	Maint.	Re-establish use zone by cutting brush back 6ft. from unit
Structural Stability		Good		
8ft. Swing Set (4Bay/8B	elts)(GameTime	Eight belt seats starting to wear	Maint.	Monitor closely
Surfacing	EWF 10-12"	Good		
		Wear mats exposed, tripping hazard	В	Bury/level mats
Use Zone		Inadequate at 14ft. in front & 12ft. in back	В	Extend to 16ft. in front & back
		Brush & branches in use zone	Maint.	Remove brush & trim back branches
Structural Stability		Good		
Environment				
	Border/Edging	Some plastic ties not level	Maint.	Level plastic ties

Notes:

It is the playground owner's responsibility to maintain the test results for the safety surfacing showing that the depth is appropriate for the fall height of the equipment in the playground.

Hazard and Maintenance Pictures Area #1

Large Composite Structure (Play & Park) Swivel Stations (2) - Wheels rattle - MAINTENANCE







Button Steps (4) - One step loose at bracket - MAINTENANCE








Double Trapeze Rings - Ten "S" - Hooks wearing - CLASS B HAZARD









Tic-Tac-Toe Panel - Panel detached at one bolt - MAINTENANCE





Music Panel - Two bolts missing - MAINTENANCE







Racing Game Panel - Two levers missing - MAINTENANCE



Geo Shapes Panel - Two bolts missing - MAINTENANCE







Flower Maze Panel - Graffiti on panel- MAINTENANCE



Radius Chain Net - Small cracks in plastisol - MAINTENANCE







Bubble Panel - Broken, sharp edges - MAINTENANCE







Cliff Climbers (2) - One panel warped (high cliff) - MAINTENANCE





Cliff Climbers (2) - Incorrect hardware at two bolts (low cliff) - MAINTENANCE







Surfacing - Several cracks, holes, edging lifting tripping hazard - CLASS B HAZARD Surface worn, repairs have gaps at edges - CLASS B HAZARD

















Freestanding Equipment (Play & Park)

Log Roll (GameTime) - Brush in use zone, 4ft. from unit - MAINTENANCE







8ft. Swing Set (GameTime) - Eight belt seats starting to wear - MAINTENANCE





Surfacing - Wear mats exposed, tripping hazard - CLASS B HAZARD





Use Zone - Inadequate, 14ft. in front & 12ft. in back - CLASS B HAZARD











Use Zone - Brush & branches overhanging - MAINTENANCE









Environment - Some plastic ties not level - MAINTENANCE



NEWFIELD ELEMENTARY SCHOOL Area #2

Overview

This playground is in fair condition. There are surfacing hazards and maintenance issues to address.

EQUIPMENT INVENTORY

Manufacturer

Small Composite Structure

Play & Park Structures









Freestanding Equipment
Talk Tubes (2)
Miracle Recreation

Sign Language Panel Game Time





Buck-A-Bout GameTime



8ft. Swing Set (4Bay/1Adaptive/6 Belts)





SURFACING MATERIAL

MANUFACTURER CONTACT INFORMATION

Crawl Thru Rock Climber Play & Park Structures



GameTime



Engineered Wood Fiber

Miracle Recreation

PO Box 420 Monett, MO 65708 800-523-4202

www.miracle-recreation.com

GameTime

PO Box 680121 Ft. Payne, AL 35968-0121 800-633-2394

www.gametime.com

Play & Park Structures

430 Chestnut Street, Suite 300 Chattanooga, TN 37402 800-727-1907

www.parkstructures.com

GEN	GENERAL PLAYGROUND ENVIRONMENT Playground Condition		ition:	FAIR	
Gen	neral Site Conditions	Condition	Hazard	Recommendation	
1	Playground Location at Facility	Right side of School			
	Number of footings in area	58			
2	Distance from roads and parking lots	100 feet			
3	Fencing-total, partial, height, type	6ft. Chain link			
4	Traffic or fence hazard	None			
5	Site conditions-level, hill, pitched	Level			
6	Drainage Problems	None			
7	Encroachment of brush or poisonous plants-where	Yes, at back use zone of swings	Maint.	Cut back brush to 16ft. From top rail of swings	
8	Bees or insects/animals noted	None			
9	Site Amenities-bench, TR, Table	TR, Picnic Table			
	Condition	Fair			
10	Border/Edging-type	Grass, Concrete, Plastic Timbers			
	Condition of edging	Good			
11	Shade Structure	Roof & Trees			
12	Signage Age Appropriate Signs/Stickers?	Yes			
	Equipment Age Appropriate, 2-5, 5-12	5-12 years			
	Adult Supervision sign or sticker?	Yes			
	Warning Signs installed?	V			
	Hard Surface	Yes			
	Heat	Yes			
	Drawstring/Strangulation	Yes			

General Site Conditions	Condition	Hazard	Recommendation
Surface Marker signs on uprights?	Yes		
Playground Rules & General Information Sign?	No	Maint.	See Notes
13 Accessibility			
Accessible Entrance 36" wide ?	Yes		
Accessible path to play area ?	Yes		
Accessible surface in use zone?	Yes		

Notes:

It is recommended that signs be installed indicating playground rules and general information.

NEWFIELD ELEMENTARY SCHOOL

AREA #2 CONDITION REPORT

		Condition	Hazard	Dagamman dation
Metal Composite St	ructuro (Play 8	Condition Park Structures)	Priority	Recommendation
Components	ructure (Flay 6	raik Structures)		
Small MaxClimb		Good		
Rung Ladder (1)		Good		
Patter Path Link		Loose in footings	Maint.	Install two new footings
Transfer Platform		Good		motali tiro non roomige
Stairs (1)		Good		
Tree Stump		Good		
Climber		2004		
Balcony Deck with Steering Wheel		Good		
Spiral Step Climber		Good		
Apex Climbing Attachment		Good		
Double Landslide Slide		Good		
Decks (4)		Good		
Roof (1)		Good		
Access Step (1)		Good		
, ,				
Surfacing	EWF 4-10"	Insufficient	Α	Add EWF & level
J		No wear mats at slide exits	С	See Notes
Use Zone		Good		
Structural Stability		Good		
Francisco Favio				
Freestanding Equip		Exposed feeting tripping	D	Cover feeting with soil or
Talk Tubes (2) (Mira	icie)	Exposed footing, tripping hazard at one talk tube	В	Cover footing with soil or surfacing
Surfacing		N/A		
Use Zone		N/A		
Structural Stability		Good		

AREA #2 CONDITION REPORT

		Condition	Hazard Priority	Recommendation
Sign Language Pa	nel (GameTime)	Good		
Surfacing		N/A		
Use Zone		N/A		
Structural Stability		Good		
Buck-A-Bout (Gan	neTime)	Good		
Surfacing	EWF 4-6"	Insufficient	В	Add EWF & level
Use Zone		Good		
Structural Stability		Slightly loose	Maint.	Monitor
Rock Tunnel Crawl Thru	(Play & Park)	One hand/foot hold cracked	Maint.	Replace one hand/foot hold
Surfacing	EWF 0-2"	Insufficient	Α	Add 6-8" of EWF & level
Use Zone		Good		
Structural Stability		Good		
8ft. Swing Set (4B (GameTime)	ay/6Belt/1Adapt.) Good		
Surfacing	EWF 0-6"	Insufficient Felt liner exposed, tripping hazard	A B	Add EWF & level Cover felt liner with EWF
		Tree root, tripping hazard Wear mats not level, tripping hazard	B B	Remove roots Bury/level wear mats
Use Zone		Brush in use zone	Maint.	Remove brush from use zone
		Inadequate at back due to brush 6ft. away	Maint.	Cut back all brush to 16ft. from center post of swing set
Structural Stability		Good		

AREA #2 CONDITION REPORT

	Hazard	
Condition	Priority	Recommendation

Notes:

There are no wear mats at the slide exits. ADA requires wear mats for accessibility and the prevention of holes at the slide exits.

It is the playground owner's responsibility to maintain the test results for the safety surfacing showing that the depth is appropriate for the fall height of the equipment in the playground.

Hazard and Maintenance Pictures Area #2

Metal Composite Structure (Play & Park Structures)
Patter Path Link - Loose in footings - MAINTENANCE





Surfacing - No wear mats at slide exits - CLASS C HAZARD



Freestanding Equipment

Talk Tubes (2)(Miracle) - Exposed footing, tripping hazard at one talk tube -





Buck-A-Bout (GameTime) - Structure slightly loose - MAINTENANCE



Crawl Thru Rock Climber (Play & Park) - One hand/foot hold cracked - MAINTENANCE





Surfacing - Insufficient at 0-2" - CLASS A HAZARD



8ft. Swing Set (3Bay/6Belt/1Adapt.)(GT) - Tree roots exposed, tripping hazard - CLASS B HAZARD





8ft. Swing Set (3Bay/6Belt/1Adapt.) - Felt exposed, tripping hazard - CLASS B HAZARD





8ft. Swing Set (GameTime) - Wear mats not level, tripping hazard - CLASS B HAZARD







8ft. Swing Set - Brush encroaching in use zone - MAINTENANCE



Use Zone - Inadequate at back due to brush 6ft. away - MAINTENANCE



