

DATE:

Playground Maintenance Corp. dba
Playground Medic
146 Broadway
Hawthorne, NY 10532
(914)741-2228 Fax (914)747-3965

Toll Free (866)332-3133 E-mail: info@playgroundmedic.com

# **PLAYGROUND SAFETY INSPECTION REPORT**

May 16, 2019

SITE:	Roxbury Elementary School 751 West Hill Road Stamford, CT 06902
CLIENT:	Stamford Public Schools Attention: Rich Lyons 888 Washington Boulevard Stamford, CT 06901
CONTACT PHONE NO.	203-977-4105
DATE OF INSPECTION:	May 1, 2019
INSPECTOR:	Natale Chionchio CPSI Certification # 41619-0521 Expiration: 5/1/2021

#### **PURPOSE AND DEFINITIONS**

#### **PURPOSE**

#### The purpose of a Playground Safety Inspection is to:

- \* Evaluate the overall condition of a playground or playgrounds at a given facility
- \* Identify hazardous conditions needing attention
- \* Identify Maintenance issues that the owner should be aware of

#### **HAZARD DEFINITIONS**

**CLASS A HAZARD:** Any condition of the playground that is life threatening or could cause severe, permanent disability.

**CLASS B HAZARD:** Any condition of the playground that could cause a serious but non-disabling injury.

**CLASS C HAZARD:** Any condition of the playground that can cause a slight injury or any condition that may not cause injury but does not meet either the Guidelines in the CPSC "Handbook for Public Playground Safety" or the ASTM F1487 "Standard Consumer Safety Performance Specifications for Playground Equipment for Public Use."

MAINTENANCE: Repairs needed or recommendations for improvement

#### STRUCTURAL STABILITY

When properly installed as directed by the manufacturer's instructions and specifications, equipment should withstand the maximum anticipated forces generated by active use which might cause it to overturn, tip, slide or move in any way.

Stability of play equipment is tested by digging around equipment footings and checking for deterioration or signs of movement that would indicate structural instability.

#### **SURFACING**

#### **DEPTH:**

The surfacing under and around the playground equipment can be a major factor in determining the injury causing potential of a fall. A fall onto a shock-absorbing surface is less likely to cause a serious injury than a fall onto a hard compacted surface. Inadequate surfacing material is usually a CLASS A HAZARD depending on the surfacing material.

The depth of surfacing material is checked by digging down to the sub base in heavy wear and low wear areas.

#### **USE ZONE:**

The surface under and around a piece of equipment onto which a child falling from or exiting from the equipment would be expected to land. These areas are also designated for unrestricted circulation around the equipment.

Use Zone is checked on all equipment by measurements in accordance with CPSC quidelines.

#### **CONDITION EXPLANATION**

Equipment and surfacing conditions will be identified as "Good", "Fair" or "Poor". This is a general classification and will indicate:

Good \* No Corrective action needed

Fair \* Some corrective action needed

Poor \* Extensive corrective action needed

# ROXBURY ELEMENTARY SCHOOL Area #1

Overview

This playground is in poor condition. The spiral slide, the suspension bridge and the dragon climber are dangerous and should be removed. The swings should be closed for use until repaired.

# **EQUIPMENT INVENTORY**

# **Large Composite Structure**

# Manufacturer GameTime













# Freestanding Equipment Curved Balance Beam - GameTime



Dragon Tire Climber Custom



**Space Shuttle - GameTime** 

8ft. Swing Set (3 Bays/6 Belt Seats)
GameTime





**SURFACING MATERIAL** 

**Engineered Wood Fiber** 

MANUFACTURER CONTACT INFORMATION

GameTime
PO Box 680121
Ft. Payne, AL 35968-0121
800-633-2394
www.gametime.com

GENERAL PLAYGROUND ENVIRONMEN
-------------------------------

**Playground Condition:** 

**POOR** 

Area #\_\_\_\_1\_\_\_ **General Site Conditions** Condition Hazard Recommendation Playground Location at Facility Front of school Number of footings in area 70 2 Distance from roads and parking lots 10 feet 3 Fencing-total, partial, height, type Total - 6 ft. 4 Traffic or fence hazard None 5 Site conditions-level, hill, pitched Level 6 **Drainage Problems** None 7 Encroachment of brush or poisonous None plants-where 8 Bees or insects/animals noted None 9 Site Amenities-bench, TR, Table Bench, TR, Table Condition Good

10 Border/Edging-type Asphalt

11 Shade Structure Trees

12 Signage

Age Appropriate Signs/Stickers?

Equipment Age Appropriate, 2-5, 5-12 5-12 years

Adult Supervision sign or sticker? Yes

Warning Signs installed?

Hard SurfaceYesHeatYesDrawstring/StrangulationYes

General Site Conditions	Condition	Hazard	Recommendation	_
Surface Marker signs on uprights?	Yes			
Playground Rules & General Information Sign?	No	Maint.	See Notes	
13 Accessibility				
Accessible Entrance 60" wide ?	Yes			
Accessible path to play area ?	Yes			
Accessible surface in use zone?	Yes			

# Notes:

It is recommended that signs be installed indicating playground rules and general information.

# **ROXBURY ELEMENTARY SCHOOL**

# AREA #1 CONDITION REPORT

AREA #1 CONDITION IN	LIONI	Condition	Hazard Priority	Recommendation
Large Composite Struct Components	ure (GameTii			
Spiral Slide		Bed way cracked & cracked at center post	В	Replace Spiral Slide
Storefront Panel Corkscrew Climber		Good Good		
Funnel Bridge Inverted Arch Ladder		Joints cracked Good	Maint.	Monitor
Suspension Bridge		One deck attachment steel broken & one deck attachment severely worn	Α	Close bridge, replace bridge and all hardware
		Bridge boards worn & cracked at joints, chains worn below	Α	
Overhead 'S' Loop Ladder		Good		
Transfer Platform Rumble & Rock Slide Above Deck Seat Barrier		Good Good Good		
Trapeze Rings		One hand hold loose Four hangers & four "S"-Hooks worn	Maint. B	Tighten one handhold Replace four "S"-Hooks & four hangers
Talk Tubes (2) DNA Climber Big Foot Slide		Good Good Good		
Tic-Tac-Toe Panel Crows Nest w/ Wheel (1)		Good Good		
Climbing Pole		Good		
Decks (12) Single Rung Access Step		Good Good		
Access Step		Good		
Surfacing	EWF 0-7"	Insufficient No wear mats at slide exits	A C	Add EWF & level See Notes
Use Zone		Good		
Structural Stability		Spiral Slide section is broken & taped off from use	Maint.	Replace slide & remove temporary barrier & caution tape

# **AREA #1 CONDITION REPORT**

		Condition	Hazard Priority	Recommendation
Freestanding Equipme Curved Balance Beam		Good		
Surfacing	EWF 3-6"	Insufficient	В	Add EWF & level
Use Zone		Good		
Structural Stability		Beam dented	Maint.	Monitor
Space Shuttle (GameTi	me)	One end stop cracked	Maint.	Replace one stop at top rail
Surfacing	EWF 0-6"	Insufficient	Α	Add EWF & level
Use Zone		Good		
Structural Stability		Good		
Dragon Tire Climber (U	nknown Mfr.)	Tires worn & cracked, exposed steel bolts/washers	В	REMOVE
		Drawstring entanglement at washers	Α	DRAGON
Surfacing	0"	Inadequate	Α	
Use Zone		None	Α	CLIMBER
Structural Stability		Tires cracked	Maint.	

#### **AREA #1 CONDITION REPORT**

			Hazard	
		Condition	Priority	Recommendation
8ft. Swing Set (GameTin	ne) ***	One seat is residential equipment, broken wood support bar with sharp edges	Α	Remove & replace with commercial equipment & hardware
		One belt broken	Maint.	Remove & replace one belt seat, chain & four clevises
		Four belts interior steel bent, all chain kinked & (16) "S"- Hooks starting to wear	Maint.	Recommend replacing four belts seats & all chain and (16) clevises
		Two hangers worn at residential seat	Α	Replace two swing hangers
Surfacing	EWF 5-10"	Insufficient	Α	Add EWF
, and the second		Wear mats exposed, tripping hazard	В	Bury/level mats
Use Zone		Good		
Structural Stability		Good		

5 belt seats, chain & clevises installed 5/11
New handicap swing seat, chain & clevises installed 5/11/19

#### Notes:

There are no wear mats at the slide exits. ADA requires wear mats for accessibility and the prevention of holes at the slide exits.

It is the playground owner's responsibility to maintain the test results for the safety surfacing showing that the depth is appropriate for the fall height of the equipment in the playground.

# Hazard and Maintenance Pictures Area #1

Large Composite Structure (GameTime)
Spiral Slide - Bed way cracked & cracked at center post - CLASS B HAZARD









Funnel Bridge - Joints cracked - MAINTENANCE











Suspension Bridge - Deck attachment steel broken & one bridge deck attachment severely worn - CLASS A HAZARD

























Suspension Bridge - Bridge boards worn & cracked at joints, chains worn - CLASS A HAZARD







Trapeze Rings - One hand hold loose - MAINTENANCE





Trapeze Rings - Four hangers & four "S"- Hooks worn - CLASS B HAZARD

















Surfacing - No wear mats at slide exits - CLASS C HAZARD







Freestanding Equipment
Curved Balance Beam (GameTime) - Dented - MAINTENANCE





# Space Shuttle (GameTime) - One end stop cracked - MAINTENANCE







Dragon Tire Climber (Unk.) - Tires worn/cracked, exposed steel bolts/washers - CLASS B HAZARD









Dragon Tire Climber - Drawstring entanglement at washers - CLASS A HAZARD













8ft. Swing Set (GameTime) - One seat is residential equipment, broken wood, support bar with sharp edge - CLASS A HAZARD

Swing repairs done 5/11/19. See condition report











8ft. Swing Set (GameTime) - One belt seat broken - MAINTENANCE



8ft. Swing Set - Four belts interior steel bent - MAINTENANCE



8ft.Swing Set (GT) - All chain kinked & (16) "S"- Hooks starting to wear - MAINTENANCE





8ft. Swing Set (GT) - Two hangers worn at residential seat - CLASS A HAZARD







# 8ft. Swing Set - Wear mats exposed, tripping hazard - CLASS B HAZARD



# ROXBURY ELEMENTARY SCHOOL Area #2

#### Overview

This playground is very poor. There are many activities that should be closed, removed or repaired. The composite suspension bridge and the swings are especially dangerous.

# **EQUIPMENT INVENTORY**

# **Large Composite Structure**















# Freestanding Equipment Space Shuttle Ride #1 GameTime



Log Roll #1 GameTime






Log Roll #2 GameTime



Chin Up Bars Unknown



8ft Swing Set (4 Bays - 8 Belt Seats)
GameTime





Trapeze Rings GameTime



Fitness Equipment - Push Up Bars



Fitness Equipment (Unknown)



Fitness Equipment - Dip Bench



**SURFACING MATERIAL** 

**Engineered Wood Fiber** 

MANUFACTURER CONTACT INFORMATION

GameTime
PO Box 680121
Ft. Payne, AL 35968-0121
800-633-2394
www.gametime.com

GEN	IERAL PLAYGROUND ENVIRONMENT	Playground Condition:	:	VERY POOR
Gen	Area #2 eral Site Conditions	Condition	Hazard	Recommendation
1	Playground Location at Facility Number of footings in area	Back of School 89		
2	Distance from roads and parking lots	200 feet		
3	Fencing-total, partial, height, type	Partial - 6ft. Chain link		
4	Traffic or fence hazard	None		
5	Site conditions-level, hill, pitched	Level		
6	Drainage Problems	Some washout of EWF	Maint.	Repair drainage
7	Encroachment of brush or poisonous plants-where	None		
8	Bees or insects/animals noted	None		
9	Site Amenities-bench, TR, Table Condition	Bench & TR Good		
10	Border/Edging-type	Wood ties & plastic timbers		
	Condition of edging	Fair		
11	Shade Structure or shade	Trees		
12	Signage Age Appropriate Signs/Stickers?	Yes		
	Equipment Age Appropriate, 2-5, 5-12	5-12 years		
	Adult Supervision sign or sticker?	Yes		
	Warning Signs installed? Hard Surface	Yes		
	Heat	Yes		
	Drawstring/Strangulation	Yes		
	Surface Marker signs on uprights?	Yes		
	Playground Rules & General Information Sign?	No	Maint.	See Notes

General Site Conditions	Condition	Hazard	Recommendation
13 Accessibility			
Accessible Entrance 36" wide ?	Yes		
Accessible path to play area ?	Yes		
Accessible surface in use zone?	Yes		

## Notes:

It is recommended that signs be installed indicating playground rules and general information.

# **ROXBURY ELEMENTARY SCHOOL**

# AREA #2 CONDITION REPORT

AREA #2 GONDINGN RE		Condition	Hazard Priority	Recommendation
Large Composite Structu	ıra (GamaTi		FIIOTILY	Recommendation
Components	ire (Gairle II	ille)		
Spiral Slide		Multiple large cracks in bed way	В	Replace slide
Rung Ladder (2)		Good		
Stairs (3)		One stair cracked at joint	Maint.	Replace one set of stairs near Tic-Tac-Toe
Arch Climber w/ Rails		Good		
Suspension Bridge		Bridge worn, chain worn, boards cracking, chain pulling through steel	Α	Close bridge - Replace bridge & two deck attachment plates
Double Wishbone Slide		Good		
Canyon Challenge		Good		
Wild Goose Trapeze Rings		Ten hangers worn	Maint.	Replace ten hangers
Wave Overhead Ladder		Good		
Twister Climber		Good		
Double Trapeze Rings		Twelve hangers worn	В	Replace twelve hangers
Climbing Pole		Good		
Mega Rock Climbers (2)		Good		
Contoured Seat Panel (1)		Good		
Funnel Bridge Link		Multiple cracks at joints	Maint.	Monitor closely
Tic-Tac-Toe Panel		Good		
Zipper Climber		Good		
Big Foot Slide		Good		
Transfer Platform		Good		
Pipe Barriers		One crack in pipe One barrier loose at Spiral Slide	B Maint.	Repair crack or replace Tighten bolt
Rung Access Steps (5)		Good		
Decks (15)		Decks wearing Holes wearing in deck, cracked with sharp edges by Tic Tac Toe	Maint. B	Monitor Replace one 48" square deck at Tic Tac Toe panel
Surfacing	EWF 4-9"	Insufficient	Α	Add EWF & level
Use Zone		Good		
Structural Stability		Good		

# **AREA #2 CONDITION REPORT**

	. •	Condition	Hazard Priority	Recommendation
Freestanding Equipment	-			
Space Shuttle Ride (#1) (		Two stops missing	Maint.	Replace two stops at rail
Surfacing	EWF 1-6"	Insufficient	Α	Add EWF & level
Use Zone		Good		
Structural Stability		Good		
Space Shuttle Ride (#2) (	GameTime)	Fenced off, unable to inspect		CLOSED OFF
Surfacing	0"	No surfacing area used as garden		REMOVE
Use Zone		J		SPACE SHUTTLE
Structural Stability				
Log Roll (#1) (GameTime	)	Bar slightly bent	Maint.	Monitor
Surfacing	EWF 0-3"	Insufficient	Α	Add EWF & level
Use Zone		Good		
Structural Stability		Good		
Log Roll (#2) (GameTime	)	Roller bar rusting	Maint.	Close until repaired
Surfacing	0"	No surfacing Exposed tree roots, tripping hazard	A B	Install 9-10" of EWF Remove roots & add 9-10" of EWF
Use Zone		Tree roots covering use zone	В	Remove roots add 9-10" EWF
		Debris in use zone	Maint.	Remove debris
Structural Stability		Good		

### **AREA #2 CONDITION REPORT**

Structural Stability

			Hazard	
		Condition	Priority	Recommendation
Chin Up Bars (Unknown N	lfr.)	Good		Close chin up bars until repaired
Surfacing	0"	No surfacing Trip hazard at tree roots Exposed footings	A B B	Add 9-12" of EWF & level Cover with EWF Cover with EWF
Use Zone		Tree roots in use zone	В	Remove roots & add 9-12" of EWF
		Overhanging tree branches	В	Cut back to 7ft. from unit

Structural Stability Good

If not installing surfacing & maintaining
Remove: Log Roll #2
Chin-Up Bars
Overhead free standing Trapeze Rings
Fitness Equipment

8ft. Swing Set (Game Time) ***	One mount turned	Maint.	Reset mount
	Sharp edges at two belt seats Fourteen bottom "S"-Hooks worn	B A	Replace two belt seats Replace (14) bottom "S"- Hooks with clevises
	Chain worn at seven belt seats	Α	Replace all chain at seven belt seats
	Chain worn at one Inclusion seat	Α	Replace chains at one Playcore Inclusion seat
Surfacing EWF 8	-12" Good Mats exposed - trip hazard	В	Bury/level wear mats
Use Zone	Good		Close until repaired
Structural Stability	Good		

\*\*\* 8 belt swing seats, chain & clevises installed 5/11/19

Freestanding Trapeze Rings (GameT	Good		Maintain area or
Surfacing 0"	No surfacing	Α	REMOVE RINGS
Use Zone	Overgrown with weeds & brush	Α	Remove all weeds & add 9- 12" EWF

Good

# **AREA #2 CONDITION REPORT**

		Condition	Hazard Priority	Recommendation
Fitness Equipment Leg Lift Push up bars Dip Bench	-	Good Good Good		
Surfacing	0"	No surfacing	Α	Add 9-12" of EWF
Use Zone		No use zone	В	Create 6ft. use zone around all equipment & add 9-12" EWF
Structural Stability		Good		

#### Notes:

It is the playground owner's responsibility to maintain the test results for the safety surfacing showing that the depth is appropriate for the fall height of the equipment in the playground.

# Hazard and Maintenance Pictures Area #2

Composite Structure
Spiral Slide - Crack in bed way - CLASS B HAZARD









Stairs - One stair cracked at joint - MAINTENANCE





Suspension Bridge - Bridge worn/chain worn, boards cracking/ chain pulling through steel - CLASS A HAZARD





















Wild Goose Trapeze Rings - Ten hangers worn - MAINTENANCE









Double Trapeze Rings - Twelve hangers worn - CLASS B HAZARD









Funnel Bridge Link - Multiple cracks at joints - MAINTENANCE









Pipe Barriers - One crack in pipe - CLASS B HAZARD





Pipe Barriers - One barrier loose at Spiral Slide - MAINTENANCE





**Decks - Decks wearing - MAINTENANCE** 





Decks - Hole wearing in deck, cracked with sharp edges by Tic Tac Toe panel -







Freestanding Equipment
Space Shuttle #1 - Two stops missing - MAINTENANCE







Space Shuttle Ridge #2 (GameTime) - Fenced off, unable to inspect





Surfacing - Area used as a garden, no surfacing - CLASS A HAZARD





Log Roll #1 - Bar slightly bent - MAINTENANCE





Log Roll #2 - Roller bar rusting - MAINTENANCE



Surfacing - No surfacing under Log Roll - CLASS A HAZARD





Surfacing - Exposed tree roots, tripping hazard - CLASS B HAZARD





Use Zone - Tree roots covering use zone - CLASS B HAZARD



Use Zone - Debris in use zone - MAINTENANCE



Chin Up Bars - No surfacing - CLASS A HAZARD





Surfacing - Exposed tree roots - CLASS B HAZARD Exposed footings - CLASS B HAZARD








Use Zone - Tree roots in use zone - CLASS B HAZARD



Use Zone - Overhanging branches - MAINTENANCE



8ft. Swing Set (GT) - One mount turned - MAINTENANCE Swing repairs done 5/11/19. See condition report.





8ft. Swing Set (GT) - Sharp edge at two belt seats - CLASS B HAZARD





8ft. Swing Set (GT) - Fourteen bottom "S" - Hooks worn - CLASS A HAZARD









8ft. Swing Set (GameTime) - Chain worn at seven belt seats - CLASS A HAZARD









8ft. Swing Set (GT) - Chain worn at one Inclusion seat - CLASS A HAZARD













Surfacing - Wear mats exposed, tripping hazard - CLASS B HAZARD



Freestanding Equipment
Trapeze Rings - No surfacing - CLASS A HAZARD





Surfacing - Overgrown with weeds & brush - MAINTENENACE



Fitness Equipment - No surfacing - CLASS A HAZARD



Use Zone - No use zone - CLASS B HAZARD







Environment

Drainage Problems - Some washout of EWF - MAINTENANCE



