Stark Elementary School

Summary of Work: March 27, 2019

Active spreadsheet of areas of concern and ongoing work completed by AAIS and Bismark uploaded to website. Please <u>CLICK HERE</u> to view the active sheet.

- Rooms 249-256- Scope of work posted on website. Work finished for 4th grade corridor. Rooms 249, 250, 254, 256 are slated to be next.

Mold Abatement in Classroom Protocol

- 1. Take off wall paper and remove all millwork, electrical and any other items
- 2. Remediate any visible mold.
- 3. Take out 1x1 section of sheetrock to see if sheetrock is impacted
 - If yes, replace the impacted sheet rock
- 4. Pain walls and put up millwork and other items.
- <u>Silver Petrucelli-</u> conducted a full site visit. <u>Report</u> posted on website.
- <u>Windows</u>- Caulking tested positive for various levels of PCBs. Samples were taken of adjacent masonry surfaces to test if PCB have leached. <u>Test Results</u> and <u>figures</u> regarding PCBs posted on website. Windows and surrounding masonry will be a summer work project to fix.
- Roof Drains- Roof drain for Room 254 was fixed on 3/18
- Planters- Removal of planters will be done in summer because they cannot be done
 when ground is frozen. Silver Pettricelli to provide alternative solutions rather than
 planters.