

[Stillmeadow](#)

Mold Task Force Spreadsheets

- [Active spread sheet of work being conducted](#)
 - [Swab test results spread sheet](#)
- Pipe insulation has been completed by KMK
 - Carpentry and electrical to put back ceiling tiles.
- Portables have been temporarily repaired. The repairs should temporarily encapsulate the exterior of the building.
 - Estimated cost \$25,000
- Tucker Mechanical HVAC assessment completed. awaiting report
- Drainage issues
 - Inadaquite Drainage by gym and front of building are causing water intrusion into the school.
 - Drain pipes have been cleaned out and are currently working with engineering to assess drainage plan.
- Roof
 - Infra-Red Analyzers
 - [Roof Scan](#)
 - [Report](#)
 - Gottfried
 - [Roof Assessment](#)
- [Water Test](#)
 - Incoming potable water tested within healthy limits.

If you have any additional questions, please email

SAMG@stamfordct.gov