Toquam Elementary School

Summary of Work: March 13, 2019

Active spreadsheet of areas of concern and ongoing work completed by AAIS and Bismark uploaded to website. Please <u>CLICK HERE</u> to view the active sheet.

- <u>Silver Petrucelli-</u> conducted a full site visit. <u>Report</u> posted on website. Awaiting mechanicals report from Silver Petrucelli.
- Roof- ¾ of Toquam Roof will be replaced over the summer. Purchase order has been processed.
- <u>Air Handlers-</u>Old, no balancing dampers were observed. Possibly frozen. Duct work is uninsulated. Determined by Bismark that they should be wrapped.
- **April Work** Work plan currently being created by Tighe and Bond for work during April break. Expect plan to be available next week.
- <u>Tighe and Bond-</u> Hygienist performed a site visit on 3/12 to provide further insight on future work plan.
- Windows above Classroom Door-Mold observed on sheetrock around the windows.
 Should be monitored in the future, possible solutions to be discussed with Silver/ petrucelli.