

EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4 Wallingford, CT 06492

Phone/Fax: (203) 284-5948 / (203) 284-5978 http://www.EMSL.com / wallingfordlab@emsl.com Order ID: 241806089 Customer ID: TIGH62

Customer PO:

Project ID: Stamford Mold Task

(860) 704-4760 Kevin McCarthy Phone: Attn: (860) 704-4775 Tighe & Bond Fax: Collected: 11/13/2018 213 Court Street Suite 1100 Received: 11/20/2018 Analyzed: 11/20/2018 Middletown, CT 06457

Proj: 28-2087-033/ STAMFORD MOLD TASK FORCE, CLOONAN MIDDLE SCHOOL (Stamford Mold Task Force)

Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Swab Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number: Client Sample ID: Sample Location:	241806089-0001 11-13-CLOON-01 Room 316 prep-ceiling tile- water stain	11-13-CLOON-02	11-13-CLOON-03	241806089-0004 11-13-CLOON-04 PTO room (1st floor)- ceiling diffuser	
Spore Types	Category	Category	Category	Category	-
Alternaria (Ulocladium)	-	-	-	-	-
Ascospores	-	-	-	-	-
Aspergillus/Penicillium	-	-	-	*Medium*	-
Basidiospores	-	-	-	-	-
Bipolaris++	-	-	-	-	-
Chaetomium	-	-	-	-	-
Cladosporium	-	-	-	*Medium*	-
Curvularia	-	-	-	Rare	-
Epicoccum	-	-	-	-	-
Fusarium	-	-	-	-	-
Ganoderma	-	-	-	-	-
Myxomycetes++	-	-	-	Rare	-
Pithomyces++	-	-	-	-	-
Rust	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-
Zygomycetes	-	-	-	-	-
Hyphal Fragment	-	-	-	Medium	-
Insect Fragment	-	-	-	-	-
Pollen	-	-	-	-	-
Fibrous Particulate	Low	Low	Low	Low	-

Sample Comment:

241806089-0004

Penicillium/Talaromyces-like conidiophores present in sample.

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected

++ = Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

= Sample contains fruiting structures and/or hyphae associated with the spores.

Gloria V. Oriol, Microbiology Manager or Other Approved Signatory

No discernable field blank was submitted with this group of samples.

Samples received in good condition unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation of the data contained in this report is the responsibility of the client.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT AIHA-LAP, LLC--EMLAP Accredited #165118

Report amended: 11/21/2018 13:30:38 Replaces initial report from:11/21/2018 12:11:30 Reason Code: Client-Change to Appearance



241806089

213 Court Street, Suite 1100, Middletown, CT 06457

Phone 860-704-4760

SAMPLE LOG FOR MICROBIAL ANALYSIS

Sheet 1 of 1

Project Name:_	Stamford Mo	ld Task Force	Project No. <u>28-2087-033</u>
	loonan	Less I	Budash Massacra K. McCarthu
Building:	Middle So	cnool	Project Manager: <u>K. McCarthy</u>
Sample ID	Sample Type	Sample Location	Material
11-13- CLOON- 01	Swab	Room 316 Prep	Ceiling Tile – Water Stain
11-13- CLOON-02	Swab	Room 211	Ceiling Tile – Water Stain
11-13- CLOON-03	Swab	Room 213	Ceiling Tile – Water Stain
11-13- CLOON-04	Swab	PTO Room (1 st Floor)	Ceiling Diffuser
- V			

Analysis Method:	☑ M041 ☐ Other		Turnaround Time 24 hours
		ove, analyses are due to Tighe & Bond nalyses will be late at 860-704-4760.	, Inc. on or before this date:
Email Results to:	frodigues@tig	hebond.com Do Not Mail Hard	Copy Report Total # of Samples:4
Special Instruction		Analysis – Fungal Direct Identification.	Note Project Specific Sample Rates
	d by: Wark Rope,	- 7	3-1 8 Time:
			18][] Time:
	d by:		
Shipped To: U	EMSL State CT	☐ Other	NOV 20 2018
			41 01 01 12 12 25

OrderID: 241806089

Gonzalez, Ivanilly

From: Frank Rodrigues <FRodrigues@TigheBond.com>

Sent: Wednesday, November 21, 2018 11:14 AM

To:EMSL Lab - WallingfordSubject:Order ID 241806089Attachments:241806089_coc (1).pdf

I incorrectly put the wrong building name on the original COC. Attached is the corrected COC. Please change. Thank you

Best Regards,

Frank

Francisco J. Rodrigues | Senior Project Compliance Specialist | FRodrigues@tighebond.com

Tighe & Bond | One University Avenue, Suite 100| Westwood, MA 02090

Direct: 781.708.9852 | Internal x4432 | Mobile 617.908.7176 <u>www.tighebond.com</u> | Follow us on: <u>Twitter Facebook LinkedIn</u>

Tighe&Bond

Please consider the environment before printing this e-mail.

OrderID: 241806089



241806089

213 Court Street, Suite 1100, Middletown, CT 06457

Phone 860-704-4760

mple Type Swab Swab Swab Swab	Sample Location Room 316 Prep Room 211 Room 213 PTO Room (1st Floor)	Project Manager: <u>K. McCarth</u>
Swab Swab Swab	Sample Location Room 316 Prep Room 211 Room 213	Ceiling Tile – Water Stain Ceiling Tile – Water Stain Ceiling Tile – Water Stain
Swab Swab	Room 316 Prep Room 211 Room 213	Ceiling Tile – Water Stain Ceiling Tile – Water Stain Ceiling Tile – Water Stain
Swab	Room 211 Room 213	Ceiling Tile – Water Stain Ceiling Tile – Water Stain
Swab	Room 213	Ceiling Tile – Water Stain
Swab	PTO Room (1st Floor)	Ceiling Diffuser
	En la company	
70		
		The second secon
all the office if a	nalyses will be late at 860-704-4760	Turnaround Time24 hours and, Inc. on or before this date: 0. ard Copy Report Total # of Samples:4
	77)	
		-13-18 Time:
		NOV 2 0 2018
F	me indicated about the office if a frodigues@tigle M041 A Mark Ropero Tank Ropero State C T	me indicated above, analyses are due to Tighe & Boall the office if analyses will be late at 860-704-476 frodigues@tighebond.com Do Not Mail Hamber Dote: Dote: Dote

J:\S\S2087 Stamford\033 Mold Remediation Consulting\Sites\Rogers_International\Laboratory Results\Mold