Tighe&Bond

Client: City of Stamford Mold Task Force

Site: Westhill High School

Job Number: S-2087-033

Photograph No.: 1 Date: 12/03/18 Direction Taken: —

Description: Black Growth on Diffuser—Room 606



Photograph No.: 2 Date: 12/03/18 Direction Taken: —

Description: Black Growth on Diffuser—Room 607





Client: City of Stamford Mold Task Force

Site: Westhill High School

Job Number: S-2087-033


Photograph No.: 3 | Date: 12/03/18 | Direction Taken: -

Description: Black Growth on Pipe Insulation—Room 511



Photograph No.: 4 Date: 12/03/18 Direction Taken: —

Description: Uninsulated Copper Piping—Room 511





Client: City of Stamford Mold Task Force

Site: Westhill High School

Job Number: S-2087-033



Photograph No.: 6 Date: 12/03/18 Direction Taken: —

Description: Water Stained Pipe Insulation—Room 402



Tighe&Bond

Client: City of Stamford Mold Task Force

Site: Westhill High School

Job Number: <u>S-2087</u>-033

Photograph No.: 7 | Date: 12/03/18 | Direction Taken: -

Description: Water Stained Drywall Above Lights—Room 402



Photograph No.: 8 Date: 12/03/18 Direction Taken: —

Description: Black Mold Growth and/or Water Stained Ceiling Tiles—Room 222



Tighe&Bond

Client: City of Stamford Mold Task Force

Site: Westhill High School

Job Number: S-2087-033

Photograph No.: 9 Date: 12/03/18 Direction Taken: —

Description: Residual Water Staining in Light Protective Cover—Room 5



Photograph No.: 10 Date: 12/03/18 Direction Taken: —

Description: Rusted Metal Track in Kiln Area—Room 10

