Capital Project Request FY 2023-2029

419 CP7912 SPECIALITY POLICE VEHICLES

Agency: 0330 Public Safety: Police - Department Wide

Contact: T. Shaw - (203) 977-4681 - tshaw@StamfordCT.gov

Location:

Neighborhood:

Voting District:

		Dept Priority	0	Tier	0
HTE Date	2021-10-12	YTD Balance			0.00
Encumbered	0.00	Amount Available			0.00
Advanced	0.00	Unfunded			0.00

Project Description	(1) Marine Division Patrol Boat \$325,	000 (2)Upgrade / Retrofit Command	1 Vehicle \$100 000
r roject bescription			

Detailed Project Cost			Justif	Justification for Inclusion in Capital Plan				Expenditures by Year						
Design Development		\$0		 Cost Savings Life Safety Continues On-Going Project Leverages Other Funds Infrastructure 				al Year	Authoriza	tion	Encumbered	l Exp	enditure	
Construction Related		\$0						021	-250,0	00.00	C	0.00	0.00	
Equipment Acquisition		\$425,000						019	250,0	00.00	C	0.00	0.00	
Miscellaneous Costs		\$0						enditures		\$0.00	\$0	.00	\$0.00	
Professional Services		\$0		lity of Life								· · ·		
Land Acquisition		\$0		Related	. 14.1.									
Art Work		\$0		Public Safety Health Mandated Legal										
FY 22/23 Total		\$425,000		 Positive Revenue Impact 										
	Positive Operational Impact/Efficiency				Method Used in Estimating Cost: Estimated change in annual o					in annual op	erating cost:			
□ Other						\$0								
Request FY 22/23					Capital Forecasts									
Funding Source	Term	Dept	Planning	Mayor	BOF	Adopted	FY 23/24	FY 24/25	FY 25/26	FY 26/27	FY 27/28	FY 28/29	Total	
Bond (City)	10	425,000	0	0	0	0	0	0	0	0	0	0	425,000	
425,000		0	0	0	0	0	0	0	0	0	0	425,000		

Comments - 1.) The current 25 year old 1997 Parker 21ft. Center console Outboard has a cracked transom due to age and wear and tear. The cost to repair is more than the boat is worth and would not be sea worthy as a patrol / rescue boat. Requesting to upgrade to a police specific patrol / rescue boat. 2.) The current Police Command Vehicle was purchased in 2006. The vehicle itself is in good mechanical repair, however, the electronics, radios, computers, cameras, and other technology are now 15 years outdated. The interior workspaces are worn and need to be replaced as well.