

EMSL Analytical, Inc.

29 North Plains Highway, Unit #4 Wallingford, CT 06492

Phone/Fax: (203) 284-5948 / (203) 284-5978 http://www.EMSL.com / wallingfordlab@emsl.com Order ID: 241901037 Customer ID: TIGH62

Customer PO:

Project ID: Stamford Mold Task

 Attn:
 Kevin McCarthy
 Phone:
 (860) 704-4760

 Tighe & Bond
 Fax:
 (860) 704-4775

213 Court Street Collected:

 Suite 1100
 Received:
 03/06/2019

 Middletown, CT 06457
 Analyzed:
 03/06/2019

Proj: 28-2087-033D/ STAMFORD MOLD TASK FORCE, NEWFIELD (Stamford Mold Task Force)

Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Swab Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number: Client Sample ID: Sample Location:	402-3	402-4	403-5 ROOM 403-WOOD DESK	241901037-0004 403-6 ROOM 403-WOOD BOOKCASE	241901037-0005 404-7 ROOM 404-WOOD BOOKCASE
Spore Types	Category	Category	Category	Category	Category
Alternaria (Ulocladium)	-	-	-	-	-
Ascospores	-	-	-	-	-
Aspergillus/Penicillium	-	-	-	-	Low
Basidiospores	-	-	-	-	-
Bipolaris++	-	-	-	-	-
Chaetomium	-	-	-	-	-
Cladosporium	-	-	-	-	*Rare*
Curvularia	-	-	-	-	Rare
Epicoccum	-	-	-	-	-
Fusarium	-	-	-	-	-
Ganoderma	-	-	-	-	-
Myxomycetes++	-	-	-	-	Rare
Pithomyces++	-	-	-	-	-
Rust	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-
Zygomycetes	-	-	-	-	-
Hyphal Fragment	-	-	Rare	-	Rare
Insect Fragment	-	-	-	-	-
Pollen	-	-	-	-	Rare
Fibrous Particulate	-	-	Rare	Rare	Rare

Sample Comment: Sample Comment: 241901037-0001 241901037-0002 None Detected

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

Denotes Not Detected.

++ = Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

= Sample contains fruiting structures and/or hyphae associated with the spores.

Gloria V. Oriol, Microbiology Manager or Other Approved Signatory

No discernable field blank was submitted with this group of samples.

Samples received in good condition unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation of the data contained in this report is the responsibility of the client.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT AIHA-LAP, LLC--EMLAP Accredited #165118

Initial report from: 03/06/2019 14:49:54

OrderID: 241901037



241901037

213 Court Street, Suite 1100, Middletown, CT 06457

Phone 860-704-4760

oject Name:_	Stamford Mo	Project No. <u>28-2087-033</u> Project Manager: <u>McCarthy</u>		
uilding: <u>New</u>	field			
Sample ID	Sample Type	Sample Location		Material
02-3	Swab	Room 402	Wood	Desk
02-4		Room 402	Wood	Desk
03-5		Room 403	Wood	Dosh
103-6		Room 403	Wood	Bookesse
404-7	Swal	Room 404	لهوه	Bookcase
•				
alysis Method: 🛭	M041 Other		Turnaround Tim	e 24 hours
sed on the turnard	ound time indicated ab ease call the office if a	ove, analyses are due to Tighe & Bond, I nalyses will be late at 860-704-4760.	nc. on or before this o	date:
ail Results to:	kmccarthy @tighe	bond.com Do Not Mail Hard Co	opy Report Total #	of Samples:5_
ecial Instruction	ns:M041 A	nalysis – Fungal Direct Identification. No	ote Project Specific Sa	imple Rates
nples collected	by: Kandy To	Date: 3/4/	19 4 3/5/19	Time:
nples [Rec'd][S	Sent by]	[Randy Taylos Date: [11 3/6/19] Time: 0709