Northeast Elementary School

Mold Task Force Summary- March 13, 2019

Active spreadsheet of work being conducted by AAIS and Viking in rooms posted on City website under school page. Please <u>CLICK HERE</u> to view the active sheet.

- Roof Roof report by Gottfried published online
- **BBS** Viking met with BBS to discuss A/E projects on 3/7. They discussed the following issues:
 - o Rooms 128-129
 - Detail for counter flashing to slab
 - Advise if the sealer top coat is required
 - Grading issue at media center
 - Skylight Assessment
 - Water damage at water fountains in classroom
- <u>Classrooms</u> AAIS removed ceiling tiles throughout; will replace when all leaks corrected; if old leak, have already or will replace ceiling tile; cleaned diffusers; cleaned and disinfected some stained roof deck; will resume work as needed after complete assessment and plan from Viking.
- Rooms 226-230- work plan by Tighe and Bond published to website.
- <u>Mechanicals</u> Tucker assessment and repair of all mechanicals for efficiency and life span i.e. rooftop ducted units and unit ventilators.
- <u>Classroom Sinks, Water fountains</u> active leaks; damaged materials. Viking is working with BBS to assess and determine how to address and correct.
- <u>Basement Art and Book rooms</u> selective demolition of drywall to assess void spaces. Need architect.
- Media Center work rooms AAIS removed ceiling tiles, cleaned effervescent, diffusers.
- <u>Art Storage Room</u> need to remove water stained pipe insulation; need to move supplies to access. Work will be performed over April break.
- Portables Closed with no plan to reopen at this point.