## **Media Center — Photographic Log**



Client: City of Stamford Mold Task Force

**Site:** Northeast Elementary School

**Job Number:** S-2087-033

Photograph No.: 1 Date: 4/18/19 Direction Taken: —

Description: Mold Growth at Drywall Base — Media Center Toilet Room

