

Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Rogers International School

Photograph No.: 1	Date: 11/13/18	Direction Taken: —
Description: Black Growth on Gypsum Wall Board—North Wall—Stage Storage 167C		

Photograph No.: 2	Date: 11/13/18	Direction Taken: —
Description: Black Growth on Gypsum Wall Board—North Wall—Stage Storage 167C		

Initial Assessment—Photographic Log

Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Rogers International School

