Tighe&Bond

Client: City of Stamford Mold Task Force Job Number: S-2087-033

**Site:** Stillmeadow Elementary School

Photograph No.: 1 Date: 11/2/18 Direction Taken: —

Description: Black Growth on HVAC Vibration Joint—Classroom 189

Photograph No.: 2 Date: 11/2/18 Direction Taken: —

Description: Black Growth on Metal Sprinkler Head—Classroom 189



Tighe&Bond


Client: City of Stamford Mold Task Force

**Site:** Stillmeadow Elementary School

**Job Number:** <u>S</u>-2087-033

Photograph No.: 3 Date: 11/2/18 Direction Taken: —

Description: Water Impacted Exterior Siding



Tighe&Bond

**Job Number:** S-2087-033

Client: City of Stamford Mold Task Force

**Site:** Stillmeadow Elementary School





Tighe&Bond

Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Stillmeadow Elementary School

Photograph No.: 7 Date: 2/7/19 Direction Taken: —

Description: Moderate Loading on HVAC Diffusers—Room 168

Photograph No.: 8 Date: 2/7/19 Direction Taken: —

**Description:** Water Damaged Window Trim—Room 168



Tighe&Bond

Client: City of Stamford Mold Task Force Job Number: S-2087-033

Site: Stillmeadow Elementary School

