Initial Assessment—Photographic Log

Tighe&Bond

Client: City of Stamford Mold Task Force Job Number: S-2087-033


Site: Stillmeadow Elementary School

Photograph No.: 1 Date: 11/2/18 Direction Taken: —

Description: Black Growth on HVAC Vibration Joint—Classroom 189

Photograph No.: 2 Date: 11/2/18 Direction Taken: —

Description: Black Growth on Metal Sprinkler Head—Classroom 189



Initial Assessment—Photographic Log

Tighe&Bond


Client: City of Stamford Mold Task Force

Job Number: S-2087-033

Site: Stillmeadow Elementary School

Photograph No.: 3 Date: 11/2/18 Direction Taken: —

Description: Water Impacted Exterior Siding



Photograph No.: 4 Date: 11/2/18 Direction Taken: —

Description: Damaged Perimeter Flashing—Exterior Roof

