

# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033M

**Site:** Rippowam Middle School

**Photograph No.:** 17 **Date:** 4/15/19 **Direction Taken:** NA

**Description:** Room 233—Tar Staining on Suspended Ceiling Tiles



**Photograph No.:** 18 **Date:** 4/15/19 **Direction Taken:** NA

**Description:** Room 227—Water Staining on Tectum Deck




# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033M

**Site:** Rippowam Middle School





# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033M

**Site:** Rippowam Middle School

<b>Photograph No.:</b> 21	<b>Date:</b> 4/15/19	<b>Direction Taken:</b> NA
<b>Description:</b> Room 224—Water Staining on Spline Ceiling Tiles		
		


<b>Photograph No.:</b> 22	<b>Date:</b> 4/15/19	<b>Direction Taken:</b> NA
<b>Description:</b> Music Office—Water Staining on Spline Ceiling Tiles		
		

# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033M

**Site:** Rippowam Middle School





# Mold Assessment — Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** 28-2087-033M

**Site:** Rippowam Middle School

<b>Photograph No.:</b> 25	<b>Date:</b> 5/1/19	<b>Direction Taken:</b> NA
<b>Description:</b> Passage to Auditorium—Stair area base—Black Mold on Gypsum Wall		
		

<b>Photograph No.:</b> 26	<b>Date:</b> 5/1/19	<b>Direction Taken:</b> NA
<b>Description:</b> Auditorium Lobby by Courtyard—Entry area base with Black Mold on Gypsum Wall		
		