



# Initial Assessment—Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** S-2087-033

**Site:** Scofield Magnet Middle School



## Initial Assessment—Photographic Log

**Client:** City of Stamford Mold Task Force

**Job Number:** S-2087-033

**Site:** Scofield Magnet Middle School

<b>Photograph No.:</b> 3	<b>Date:</b> 11/14/18	<b>Direction Taken:</b> —
<b>Description:</b> Staining on Floor Tile—Kitchen Office		

<b>Photograph No.:</b>	<b>Date:</b>	<b>Direction Taken: —</b>
<b>Description:</b>		