Initial Assessment—Photographic Log

Tighe&Bond

Client: City of Stamford

Job Number: S-2087-033

Site: Scofield Magnet Middle School

Photograph No.: 1 Date: 8/7/19 Direction Taken: —

Description: Room 237A—Visible Mold Growth on Sheetrock under Skylight



Photograph No.: 2 Date: 8/7/19 Direction Taken: —

Description: Room 237A—Visible Mold Growth on Sheetrock under Skylight



Initial Assessment—Photographic Log

Tighe&Bond

Client: City of Stamford

Site: Scofield Magnet Middle School

Job Number: S-2087-033



