Stamford High School

- Summer work to be discussed in a separate meeting this Friday,
 June 14th
- Tucker Mechanical assessing belimo valves in Stamford High and Stillmedow. Belimo valve rep coming this Thursday, 6/13
- Structural Engineer to be obtained to assess wood framing above plaster ceiling.
- Tighe and Bond in process of creating a cleaning plan for Stamford High School, focusing this summer on 1927 building.
- Roofs
 - o Roof Scan performed by infra-red analyzers.
 - o Gottfried has performed a site visit.
 - Roof in 27 building in poor condition. Gottfried
 - Slate roof on steeple in poor conditions
- Areas of Concern that will need to be addressed
 - 1927 Building Exploring possibility of closing for the summer to perform work above plaster ceilings, the plywood structure above ceiling and floor.
 - o 600 Wing
 - 10,000 feet of sheetrock with Asbestos taping.
 - o Boyle Stadium
 - Locker Room.
 - Lockers need to be ripped out and replaced.
- City to engage structural engineer that has done prior work in the building.

If you have any additional questions, please email Moldtaskforce@stamfordct.gov