

## Stamford High School

- Belimo Valves
  - Tucker Mechanical to begin replacement of Belimo valves at Stamford High School, beginning in the 27 building.
  - Engineer to provide a site survey of all Belimo valve locations in the school.
  - [Water Test Results](#)
    - Incoming potable water tested within healthy limits.
- 1927 Building
  - [Structural Engineering report online](#)
  - Active leaks being repaired
- Boyle Stadium
  - Locker Room
    - Lockers replaced with lockers from old police station
    - Tucker evaluating locker room HVAC
- Rooms 202, 204, and 209
  - Ceiling asbestos abatement completed
  - Engineer visiting this Friday, 8/23 to assess structural and floor issues
    - Engineer to asses holes cut in floors
- Courtyard Waterproofing
  - Pump chamber to be delivered this Friday, 8/23
  - 25 loads of blasted rock hauled out of courtyard
  - Capasso has started waterproofing
    - 45-55 percent of the wall has been waterproofed
  - Will not be completed before start of school
    - Loud noise work will be finished

- HVAC
  - Tucker Mechanical
    - [HVAC Assessment](#)
- Roofs
  - Infra-red Analyzers
    - [Model](#)
    - [Report](#)
  - Gottfried Roof Report
    - Roof replacement pending review of submittals by BBS
    - Discussion with engineer this Friday, 8/23
    - Following roof replacements projects are scheduled.
      - Slate roof
      - Roof A North Phase 1
      - Roof A South
        - Note: These sections are all located in the front of the building.
- Boilers
  - Tucker to perform an evaluation of boilers starting tomorrow, 8/21
  - Pricing for repairing or replacing boilers to be provided
- 12 fans and 3 dehumidifiers have been rented and installed by Viking Construction to assist in improving air circulation and moisture levels over the summer.

If you have any additional questions, please email

**[SAMG@stamfordct.gov](mailto:SAMG@stamfordct.gov)**