## **Initial Assessment—Photographic Log**

Tighe&Bond

Client: City of Stamford Mold Task Force

**Site:** Arts—Leap

**Job Number:** S-2087-033

Photograph No.: 1 Date: 11/16/18 Direction Taken: —

**Description:** Room 1 Rear Area—Water Stained and Damaged Ceiling Tiles



Photograph No.: 2 Date: 11/16/18 Direction Taken: —

**Description:** Room 1—Water Stained Ceiling Tiles



## **Initial Assessment—Photographic Log**

Tighe&Bond

Client: City of Stamford Mold Task Force

**Site:** Arts—Leap

**Job Number:** <u>S-2087-</u>033


Photograph No.: 3 Date: 11/16/18 Direction Taken: —

**Description:** Room 5 —Water Stained Ceiling Tiles



Photograph No.: 4 Date: 11/16/18 Direction Taken: —

**Description:** Room between 5 & 6 —Water Damaged Paint



## **Initial Assessment—Photographic Log**

Tighe&Bond

Client: City of Stamford Mold Task Force

**Site:** Arts—Leap

**Job Number:** <u>S-2087-033</u>

Photograph No.: 5 | Date: 11/16/18 | Direction Taken: -

**Description:** Room 10 Rear Area —Water Stained Ceiling Tiles



Photograph No.: 6 Date: 11/16/18 Direction Taken: —

Description: Room 10 Rear Area—Water Staining on CMU Wall

