Initial Assessment—Photographic Log

Tighe&Bond

Client: City of Stamford Mold Task Force

Site: BOE Areas— Stamford Government Center

Job Number: S-2087-033

Photograph No.: 1 Date: 12/17/18 Direction Taken: —

Description: 3rd Floor Women's Toilet Room—Growth Behind Vinyl Covering



Photograph No.: 2 Date: 12/17/18 Direction Taken: —

Description: 3rd Floor Women's Toilet Room—Water Stained Drywall



Initial Assessment—Photographic Log


Tighe&Bond

Client: City of Stamford Mold Task Force

Site: BOE Areas— Stamford Government Center

Job Number: <u>S-</u>2087-033





Initial Assessment—Photographic Log

Tighe&Bond

Client: City of Stamford Mold Task Force

Site: BOE Areas— Stamford Government Center

Job Number: <u>S</u>-2087-033

Photograph No.: 5 Date: 12/17/18 Direction Taken: —

Description: 3rd Floor Cubicle Area—Water Stained Pipe Insulation



Photograph No.: 6 Date: 12/17/18 Direction Taken: —

Description: 5th Floor Women's Toilet Room—Vinyl Covering at Toilet Room Stall

